



Colotemp

Color Change Crayons

Instructions for Use

Mark preheated surface where the measurement is desired

Immediate color change indicates that the measurement surface is higher than the crayon rating

A color change after (2) two seconds indicates that the measurement surface is lower than the crayon rating

Accuracy $\pm 5^{\circ}$ C